

## 1/2" Injector Socket, 10 mm Internal Hexagon (Art. 4478)



- for loosening the retaining ring of injectors  
is needed for injector disassembly
- with 7.5 mm bore

Technical modifications reserved - we are not responsible for issues while printing